



























OEM□□□□



# OEM PROCESS



01  
artwork from customer



02  
make the quotation



03  
make the sample for you confirmed place the order



04  
mass production inspection packing



05  
shipment

## PRODUCTION PROCEDURES




1. EDGE STITCH




2. CUT FABRIC



3. SEWING



4. TIP ASSEMBLY



5. SEW UP



6. QUALITY CHECK



XXXXXXXXXXXXXXXXXXXXXXXX

XXXXXXXX

Free design service

Factory production halls

Umbrella sample room

Quick Response...  
99.9%  
compared with t...  
LOTUS UMBRELLA

24 hours on line.

We focus on manufacture umbrella for 19 years, we can do it better, fast.  
Customized with low MOQ, Free sample, Free design, Shipping fast, Quick response

XXXXXX

**1. XXXXXXXXXXXXXXXXXXXXXXX**

XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX19XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX

**2. XXXXXXXXXXXXXXXXXXXXXXX**

XX5XXXXXXXXXXXXXXXXXXXXXXXXXXXX

XXXXXXXXXXXXXXXXXXXX

T / T30XXXXXXXXB / LXXXXXX70XXXXXXXX

XXXXXXXXXXXXXXXXXXXX

ETD 25-35

## 5. 5.1

I. AQL 2.5 // 4.0

II. QC

III. QC AQL